

**Uniform Mitigation Verification Inspection Cover Pages**

**For:** Mr. & Mrs. Smith2

**Date:** 12/01/2015



Front of structure



Right Side of structure



Left Side of structure



Back of structure



Pool

**Uniform Mitigation Verification Inspection Cover Pages**

For: Mr. & Mrs. Smith2

Date: 12/01/2015



Single clips



8 D nail decking attachment.

**Uniform Mitigation Verification Inspection Cover Pages**

For: Mr. & Mrs. Smith2

Date: 12/01/2015



Nail spacing



Hip and gable roof

## Uniform Mitigation Verification Inspection Cover Pages

For: Mr. & Mrs. Smith2

Date: 12/01/2015



Roof

Permit information is received from the County and Cities. This data may be incomplete and may exclude permits that do not result in field reviews (for example for water heater replacement permits). We are required to list all improvements, which may include unpermitted construction. Any questions regarding permits, or the status of non-permitted improvements, should be directed to the permitting office in which the structure is located. **Permit Number**

Description	Issue Date	Estimated Value
<a href="#">CW15-02146</a>	09 Mar 2015	\$19,000